



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Supervisor 1027

Inspection Report
Minerals Regulatory Program
Report Date: June 8, 2005

Mine Name: Pelican Point Quarry
Operator or Permittee Name:
Pelican Rock Rock Products
Permittee Mailing Address:
1565 North Redwood Road
P.O. Box 704
Lehi, Utah 84043

Permit number: M/049/011
Inspection Date: June 7, 2005

Inspector(s): Doug Jensen, Lynn Kunzler, Daron Haddock
Other Participants: Lance Heaton, Patrick Collins

Weather: Cool, Rainy
Inspection Start Time: 9:00 AM
Inspection End Time: 10:30 AM
Site location/Area Inspected (i.e. Pit #):
Quarry
Surface Ownership: Fee/SITLA
Mineral Ownership: Fee/SITLA
Mineral Mined: Limestone
Type of Mine: Quarry

Permit Status: Active
Current Acreages:
Total Permitted (Bonded): 33 acres
Total Disturbed: ?????

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Met on site with Rockwell's consultant, Patrick Collins – Mt. Nebo Scientific, to ground truth a recent map of the quarry.

Inspection Date: June 7, 2005; Report Date: June 8, 2005

Page 2 of 2

M/049/011

Inspection Summary:

1. Permits, Revisions, Transfer, Bonds. The transfer and reclamation contract on this site needs to be completed as soon as possible. The revision of the reclamation plan should also be submitted within the next month, to allow the quarry to come back into compliance.

Rockwell Construction Products recently took over this quarry and is in the process of completing the transfer of the permit and reclamation contract.

This site is presently operating under a Division Directive for failure to furnish maps as requested by the Division on August 13, 2004, for the purpose of bond escalation. Rockwell has hired Mt. Nebo Scientific to update their reclamation plan that will include updated maps of the quarry.

This quarry has areas within the permit area that were initially described as pre-law in the original permit application. Some of these areas have been merged into Pelican's present operation; therefore will need to be included in the new permit. This was the purpose of the inspection, to review these areas which Mt. Nebo has plotted on a recent aerial photo – contour map.

We traveled around the site to look at these areas. After the tour, it was agreed that the areas shown on the map was sufficient to reflect the areas presently being used by Rockwell.

Mr. Heaton indicated that an asphalt plant and a concrete batch plant could be sited on a pre-law area (an area where an asphalt plant had been located near Redwood Road) in the future. He was curious as to whether these plants, because of their proximity to his quarry and the fact that they would buy material from the Rockwell quarry, would need to be a part of their plan. We stated that because these plants would be owned and operated by others, they would not be considered a part of his operation.

After the tour we left the site.


Directions to the site:

The quarry is located south of Lehi, Utah on Redwood Road.

GPS data:

None gathered.

Inspector's Signature



Date: June 8, 2005

DJ:jb

cc: Lance Heaton, operator
Patrick Collins, Mt. Nebo Scientific
John Blake, SITLA

O:\M049-Utah\m0490011-pelicanpoint\inspections\insp-06072005.doc